

# Design Standards Letter

Letter Number: **G-1986-06**

Letter Date: **09/12/1986**

Effective Date: **11/01/1986**

Section/Plan No.: **S0101, S0622, S0712, S0613**

Subject: **Revised General Special Provisions and Form SP-14**

Body

-----  
Attached are copies of revised General Special Provisions and Form SP-14.

A brief description of the latest revisions follows:

**SP-14. Sec 101 Definition of Terms, Sec 613 Pavement Repair, Sec 622 Temporary Pavement Marking and Sec 712 Structural Steel Construction have been added.**

**Sec 101. Holidays were revised to include the third Monday in January as Martin Luther King Day and to delete from the list the General Primary Election Days and General State Election Days.**

**Sec 613. This section has been completely revised to incorporate the approved Design Committee action with regard to pavement repair. The following bid items are to be used for pavement repair items effective with the November, 1986 letting.**

**613-20.00 0.1 Sq. Yd. Pavement Repair (Concrete)**

**613-20.01 1.0 Sq. Yd. Subgrade Compaction (6 inch Depth)  
(Pavement Repair)**

**613-20.02 1.0 Sq. Yd. Type 3 Aggregate For Base  
(4 in. Thick) (Pavement Repair)**

**613-20.03 1.0 Lin. Ft. Vertical Saw Cuts (Full Depth)**

**613-20.04 1.0 Lln. Ft. Vertical Saw Cuts (Partial Depth)**

**613-20.05 1.0 Each Dowel Bars (Drilling, Furnishing,**

and Installing)

**613-20.06 0.1 Sq. Yd. Partial Depth Pavement Repair  
(Concrete)**

**613-20.07 0.1 Sq. Yd. Partial Depth Pavement Repair  
(Bituminous)**

**Sec 622. Revised to conform with the length and intervals of temporary pavement marking in accordance with the latest MUTCD requirement.**

**Sec 712. Revised to require that the mill test report must state the location of the mill where the molten metal was produced.**

**The above revisions are effective with the November, 1986 letting.**