

Design Standards Letter

Letter Number: G-1996-13

Letter Date: 10/30/1996

Effective Date: 01/01/1997

Section/Plan No.: S0107, S0202, S0403, S0616, S0617, S0902, S1000, S1045

Subject: Revisions to Job Special Provisions

Body

The following revisions, additions, and deletions to the Support Center Job Special Provisions are effective for the January Bid Opening. Enclosed are printed copies of the revised and new special provisions.

REVISIONS:

Miscellaneous

Index By Section TITLES
Alphabetical Index TITLES1

Each index changed to reflect current revision dates and filenames.

SECTION 107 - Legal Relations and Responsibility to the Public

General - Federal DSP-90-11F FEDERAL
General - State DSP-90-11E STATE

Revised effective date for State Wage Rates to 12/01/96 and for Revised Standard Plans to 01/01/97.

Training Special Provision DSP-90-11A TRAINING

Changed "Missouri Highway and Transportation Department" to "Missouri Department of Transportation."

SECTION 202 - Removals

Disposition of Existing Signal/Lighting Equipment DSP-93-11A DISPOSIT

Changed "Missouri Highway and Transportation Department" to "Missouri Department of Transportation."

SECTION 616 - Traffic Control Plan

Changeable Message Sign (Commission Furnished) DSP-93-09C CMSCOMM
Changeable Message Sign (Contractor Furnished) DSP-94-05C CMSCONTR
Changeable Message Sign (Solar Powered - Commission Retained)
DSP-96-10A CMSSOLAR

Changed area code in telephone number for American Signal Company from "404" to "770" and/or changed "MHTD" to "MoDOT".

Impact Attenuator (Sand Barrels) DSP-92-04B BARRELS

Eliminated requirement of proprietary "Fitch" and "Energite" modules and changed "MHTD" to "MoDOT."

SECTION 617 - Concrete Traffic Barrier

State Furnished Conc. Traffic Barrier and Relocating Temporary Traffic Barrier DSP-93-09D STTRAFBA

Revised to include loading and unloading the barriers as the contractor's responsibility. Changed instructions from contacting "District Maintenance Office" to contacting "District Engineer."

SECTION 902 - Traffic Signals

Type 170 Signal Controller DSP-95-03B 170SPEC

Changed "MHTD" to "MoDOT."

SECTION 1000 - Materials Details

High Range Water-Reducing Admixtures MSP-92-09B MSP9209B

Makes editorial changes to comply with the present Division

Engineer of Materials title.

ADDITIONS:

SECTION 902 - Traffic Signals

Changes to Metric 1996 Standard Specifications for Highway Construction DSP-97-01 DSP9701

Proposed revisions to Standard Specifications for signal mast arms to add welding codes, inspection, and certification requirements. This special provision shall be used until the proposed revisions to Section 902.4.3.3 of the Standard Specifications are approved.

SECTION 1045 - Paint for Structural Steel and Wood

Calcium Sulfonate Paints for Steel MSP-96-13 MSP9613

Combines Calcium Sulfonate/Alkyd Primer (MRSP-91-06F), Calcium Sulfonate Rust Penetrating Sealer (MRSP-91-07A), and Gray Calcium Sulfonate/Alkyd Topcoat (MRSP-91-08F).

DELETIONS:

SECTION 403 - Asphaltic Concrete Pavement

*Stone Mastic Asphalt MRSP-92-06L MSP9206L

SMA is a standard 403 mixture in the 1996 Missouri Standard Specifications for Highway Construction, therefore the special provision is no longer needed.

SECTION 902 - Traffic Signals

Traffic Signal Post DSP-92-04A POST

Removed pending revisions to signal mast arm standard drawings. Do not use until further notice.

SECTION 1045 - Paint for Structural Steel and Wood

Calcium Sulfonate/Alkyd Primer MRSP-91-06F MSP9106F

Calcium Sulfonate/Rust Penetrating Sealer MRSP-91-07A MSP9107A
Gray Calcium Sulfonate/Alkyd Topcoat MRSP-91-08F MSP9108F
Tan Calcium Sulfonate/Alkyd Topcoat MRSP-94-01A MSP9401A
Green Calcium Sulfonate/Alkyd Topcoat MRSP-94-04 MSP9404

These special provisions will no longer be used due to the new paint policy implemented in MSP-96-13.

bah
Enclosures