

Design Standards Letter

Letter Number: G-2004-03

Letter Date: 04/19/2004

Effective Date: 07/01/2004

Section/Plan No.: none

Subject: Revisions to Job Special Provisions (JSPs)

Body

Questions concerning the distribution of revisions to job special provisions should be directed to Central Office-Design, Design Standards Section, Michael M. Qutami (573) 526- 4331 or Joseph G. Jones (573) 751-3813.

NOTES	EXPLANATION
1	The following listing shows the additions, revisions and deletions made to the Central Office Job Special Provisions between January 10, 2004 and April 16, 2004.
2	Current Job Special Provisions can be viewed on the MoDOT Web Page under the heading "Standards and Specifications" from the menu selection "Business" or at: http://www.modot.org/business/standards_and_specs/jobspecialprovisions.htm
3	Designers, consultants and construction personnel can quickly access the latest revisions of the Job Special Provisions by viewing the AGC Updates in MoDOT's JSP Lotus Notes database. The JSPs compiled in the AGC (Associated General Contractors) Updates are in revision mode so that the viewer can easily identify the changes made to the JSP.

SECTION	DESCRIPTION OF REVISION	EFFECTIVE DATE
SEC 0102	Bidding Requirements and conditions	
	Project Contact for Contractors/Bidder Questions DSP-96-05C	N/A
	Revised to change GHQ to Central Office. Corrected the e-mail address.	
SEC 0108	prosecution and progress	
	Contract Time For Completion of Work DSP-90-01F	01/2004
	Revised the wording in the last sentence of Sec 1.3.	

SEC 0201	CLEARING AND GRUBBING	
	Job Site Litter, Debris and Mowing Management DSP-04-09	07/2004
	This is a new JSP resulted from a task force. It is intended to control and remove litter, debris and excessive vegetation within the project limits in high visibility urban areas. It will be incorporated into the spec book if it gains wide acceptance and get used frequently.	
SEC 0403	asphaltic concrete pavement	
	Alternates for Pavements DSP-96-04G	01/2004
	To eliminate conflict with Pavement Specifications for Alternate Bids DSP-03-10, Sec 3.0 was changed to reference payment in accordance with Sec 502.14 of the pavement specification for alternate bids job special provision instead of payment in accordance with 502.18 of the standard specifications.	
SEC 0505	bridge deck concrete wearing surface	
	High Performance Concrete for CIP Bridge Decks MSP-98-12F	03/2004
	Deactivated this Job Special Provision on request from RDT. The current MSP has yielded unsatisfactory results. RDT is working on alternate special provision.	
The following changes are the result of the conversion to the Performance Specifications:		
These JSP's will be deleted from the current database and incorporated into the Performance Specifications:		
SEC	TITLE & ID	07/2004
102	Asphalt Binder Maximum Allowed Payment DSP-99-07N	
104	Protection of Railroad Facilities and Traffic DSP-93- 08D	
105	Contractor Furnished Surveying and Staking DSP-01-08	
105	Division 100 Revisions for Non-Complex Projects DSP-97-06D	

108	Nighttime Construction Operation DSP-93-20A	
108	Working Day Count (Bridges) DSP-90-03A	
201	Tree Clearing Time Restriction DSP-03-07	
203	Contractor Furnished Borrow Guidelines DSP-98-24A	
203	Embankment in Place (Contractor Furnished Borrow) DSP-93-34J	
203	Embankment in Place (Contractor Furnished Borrow) DSP-94-07F	
403	Aggregate QC/QA MSP-96-02K	
403	Bituminous Mixture QC/QA MSP-96-01V	
403	Material Transfer Vehicle (MTV) DSP-98-30A	
403	Payment of Bituminous Material By Square Yard (Meter) DSP-98-10H	
403	Superpave Asphaltic Concrete Pavement MSP-95-03Z	
404	Bituminous Mixing Plants MSP-00-03	
405	Reclaimed Bituminous Material MSP-04-01	
413	Preventive Maintenance Treatments DSP-02-08B	
501	Epoxy Polymer Concrete Overlay MSP-00-01	
502	Accelerated PCCP Concrete MSP-96-16B	
502	Ultra-thin Concrete Whitetopping MSP-98-09E	
608	Truncated Domes DSP-02-10A	
613	Partial Depth Pavement Repair of An Existing Bituminous Overlay DSP-00-08	
613	Class A Partial Depth Pavement Repairs DSP-03-06	
616	Changeable Message Sign (Contractor Furnished/Retained) DSP-94-04J	
616	Impact Attenuator (Sand Barrels) DSP-92-01H	
616	Radar Speed Advisory System DSP-92-02B	
616	Solar- Powered Portable Traffic Signal System (Commission Furnished) DSP-98-05A	
616	Temporary Traffic Signals and Lighting (two-way, Single Lane Operation) DSP-95-04D	
616	Traffic Barrier Delineator DSP-98-20D	
616	Truck Mounted Attenuators (TMA) DSP-90-02F	
617	Station Numbers on Concrete Traffic Barrier DSP-93-24B	
620	Acrylic Copolymer Fast Dry Traffic Marking Paint MSP-98-08F	
622	PCCP Diamond Grind Texturing MSP-96-19F	
622	Stockpiling Cold milled Material (Contractor Retained) DSP-00-10	

623	Epoxy Polymer Concrete Overlay MSP-00-01	
627	Contractor Furnished Surveying and Staking DSP-01-08	
628	Fiberized Crack Sealing (Bituminous and Concrete Pavement) DSP-01-14	
628	Pavement Crack Sealing (PCCP) DSP-01-15	
628	Pavement Crack Sealing (Bituminous Pavement) DSP-01-16	
806	Temporary Stream Crossing DSP-01-05	
902	Fiber Optic Closed Loop Interconnect System DSP-00-05	
902	Twisted Pair Closed Loop Interconnect System DSP-00-07	
902	Type 170 Signal Controller DSP-95-03E	
902	Wireless Closed Loop Interconnect System DSP-01-12	
903	Commission Furnished Signs DSP-97-08B	
1045	Calcium Sulfonate Primer for Steel MSP-00-05	
1045	Calcium Sulfonate Sealer for Steel MSP-00-06	
1045	Calcium Sulfonate Topcoat for Steel MSP-00-07	
1045	Calcium Sulfonate/Polymer Primer MSP-96-06D	
1045	Calcium Sulfonate/Polymer Topcoat MSP-96-05D	
1045	Rust Penetration Epoxy Sealer MSP-96-07C	

These JSP's will be deleted from the current database and will be incorporated into the General Provisions:

SECTITLE & ID07/2004

107Section 404 Nationwide Permit No. 12 DSP-98-13C

107Section 404 Nationwide Permit No. 13 DSP-93-25G

107Section 404 Nationwide Permit No. 14 DSP-93-01H

107Section 404 Nationwide Permit No. 15 DSP-95-02E

107Section 404 Nationwide Permit No. 23 DSP-93-02H

107Section 404 Nationwide Permit No. 3 DSP-93-15H

107Section 404 Nationwide Permit No. 33 DSP-94-02H

107Railroad's Protective Liability Insurance DSP-94-06C

107Disadvantage Business Enterprise Contract Provision DSP-98-08A

107Disadvantage Business Enterprise Program Compliance Certificate DSP-02-09

108Training Special Provision DSP-90-07F

These Specs will be added to the current JSP database:

These spec sections were seldom used. They were removed from the spec book and added to the JSP database.

SECTITLE & ID07/2004

0405Reclaimed Bituminous Material MSP-04-01

0610Masonry Construction DSP-04-06

0615Office for the Engineer DSP-04-07

0729Placing State Owned Pipe DSP-04-08
--

0903Overhead Lighting of Signs DSP-04-09
--