

Design Standards Letter

Letter Number: P-1983-03

Letter Date: 02/25/1983

Effective Date: 04/01/1983

Section/Plan No.: P604.05, P604.10, P604.11, P604.12, P604.13, P604.14, P604.15, P604.21, P604.22, P604.23, P604.24, P604.25, P604.26, P604.27, P604.28, P604.29, P606.30, P610.20, P616.10, P725.31, P806.00, P903.05, P903.06, P903.07

Subject: Revised Drawings and Form SP-2

Body

ALL DIVISION AND DISTRICT ENGINEERS:

We are in the process of revising and reprinting the Book of Standard Plans. This is the second of two submittals.

Attached are copies of the above noted revised Standard Plans with revisions as follows.

The following drawings have been redrawn for clarity.

604.05A 604.22b 606.30E
604.10B 604.23B 610.20E
604.11B 604.24B 725.31C
604.12B 604.25B 806.00C
604.13B 604.26C 903.05C
604.14B 604.27C 903.06C
604.15B 604.28D 903.07C
604.21B 604.29C

606.10B Sheet 1 of 2. This drawing has had numerous revisions. The major revisions are as follows:

1. The Type III Barricade has been deleted. A detail of the movable barricade has been added to the drawing and indicates sign mounting height when drums are located in front of the barricade.
2. The requirements for the flashing arrow panel have been revised to prohibit use of the sequential chevron mode of operation.

3. The mounting height of Type I and Type III Object Markers has been revised.
4. The drum has been added to the detail for portable sign mounting. A requirement for mounting height of regulatory signs on portable mounts has been added.

Sheet 2 of 2. The major revisions are as follows:

1. The minimum sign, symbol, and legend sizes have been increased on most signs.
2. Several symbol signs have been deleted.
3. Distance and message plates have been added to several signs in the warning series. These plates are to be included with each sign where shown.

The above revisions are effective with the April, 1983 letting.

James F. Roberts
Division Engineer
Surveys and Plans